



American Gilsonite Company

Bonanza, Utah 84008 • Phone (801) 789-1921

FAX (801) 789-1956

Bonanza Mining Operations

January 13, 1993

Mr. D. Wayne Hedberg, Permit Supervisor
UTAH DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203


Re: Annual Report for the Year 1992

Dear Mr. Hedberg:

Enclosed is the Annual Report of 1992 for Mine No. M/047/010.
This is the Bonanza Mine of American Gilsonite Company with
operating offices in Bonanza, Utah.

Should you have any questions please contact me at 789-1921,
extension 15.

Sincerely,


Neldon Kunz
Mine Superintendent

NHK/dns

RECEIVED
JAN 14 1993
DIVISION OF
OIL GAS & MINING

RECEIVED

JAN 14 1993

DIVISION OF
OIL GAS & MINING

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) 01/92 To (mo./yr.) 12/92
2. DOGM File Number: M/047 / 010
3. Mine Name: American Gilsonite Company, Bonanza Operations
4. Mineral(s) Mined: Gilsonite
5. Legal Description (Location of Lands Affected): Uintah County
 1/4, 1/4, Section , Township , Range
 1/4, 1/4, Section , Township , Range
 1/4, 1/4, Section , Township , Range
6. Name of Operator or Company: American Gilsonite Company
7. Permanent Address: Mine Site
Bonanza, Utah 84008

8. Company Representative (or designated operator):

Name: Neldon Kunz
Title: Mine Superintendent
Address: Bonanza, Utah 84008
Phone: (801) 789-1921

☒ Please check if any of the above information has changed since previous year.

II. MINING AND RECLAMATION

1. Was the mine active during the past year? Yes ☒ No ☐

2. If active, how much ore or mineral was mined? 29,296 tons

3. How much new or additional acreage was affected during past year? 1

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

Set up one new mine site (I-30) on State Mineral
Lease ML-31934

5. How much acreage was reclaimed during past year? 0

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

7. What is the total disturbed acreage at years end? Approximately 49 acres.

8. Briefly summarize mining and reclamation planned for the upcoming year.

No additional mine sites are planned and it is not
expected that any will be mined out, and therefore no
reclamation is planned.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. ADDITIONAL INFORMATION

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Neldon Kunz

Title of Operator: Mine Superintendent

Signature of Operator: 

Date: 1/13/93

jb
MR-AR